

ANACONDA Minerals Company  
New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
Telephone 505 876 2211

*Handwritten:* Please see comprehensive sample Env file



*Handwritten:* 10/17/84

October 10, 1984

04 OCT 17 A 9:02

Minerals Staff  
Rio Puerco Resource Area  
Bureau of Land Management  
3550 Pan American Freeway, N.E.  
P. O. Box 6770  
Albuquerque, N.M. 87107

*Handwritten:* ALBUQUERQUE, N.M.

Dear Sir:

The Third Quarter of 1984 sampling data for Anaconda's former Jackpile minesite leases is submitted as follows:

1. Radiological Analysis of Surface Water;
2. Chemical Analysis of Surface Water;
3. Maps Showing Surface Water Sampling Locations;
4. Results of the Air Monitoring Program;
5. Results of the Ambient Radon Monitoring Study;
6. Map showing location of Air and Radon Monitoring Stations;
7. Map of Groundwater Monitoring Locations; and,
8. Chemical Analysis of Groundwater Monitoring, Third Quarter.

Please note that the Pb-210 results for air monitoring will be forwarded upon our receipt of those results.

Sincerely,

*Handwritten signature of Dean L. Roberts*

Dean L. Roberts  
Chief Environmental Engineer

mls

Enclosures

pc: CES, CDW, MAS